Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080152-5

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2951 E. COLORADO ST., PASADENA, CALIF.

No. 11616

RECEIVED FROM

DATE REC'D. 3-1-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	OR	ACCT. OR W.O. NO. / S.O. NO.
	322		21		3	1				

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
100	73-002-2 Bearing - Ball New Hampshire #21r	100	✓	

RECEIVED BY [signature] INSPECTED BY DWQ DATE 3/22/57 REJECTS RETURNED ON SHIP. MEMO NO.

HMC-1088

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2951 E. COLORADO ST., PASADENA, CALIF.

No. 11617

RECEIVED FROM MILLI-WATCH CORP.

DATE REC'D. 3-1-57

P.O. NO. 4452

VENDOR PACKING SLIP NO. 250

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	OR	ACCT. OR W.O. NO. / S.O. NO.
	322	000000	89	0	23	1				

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
16	73-129-2A Mill Watch Part	16	✓	

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080152-5

RECEIVED BY [signature] INSPECTED BY DWQ DATE 4/23/57 REJECTS RETURNED ON SHIP. MEMO NO.

HMC-1088